

H-K Building #: 35
 Project Number: 0980193E
 Project: G. HEILEMAN BREWERY "E"
 Date Inspected: 03/23/89
 Inspector: BAXTER & VOTH

ASBESTOS ASSESSMENT SURVEY

Building Number: 35
 Building Name: BOTTLING HOUSE
 SEATTLE, WASHINGTON
 Building Type: FOOD PROC.
 Year Constructed: 1955

*****	AREA NUMBER: 10	AREA DESCRIPTION: 2nd Floor-Mezzanine-Ceilings	AREA AVERAGE % ASBESTOS: 0%	*****
-------	-----------------	--	-----------------------------	-------

LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	QUANTITY	UNITS OF MEASURE	PIPE ID	EXP POT	PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
bottling QC lab	18-356056	0%	drop or lay-in panel	OMG	125	sq.ft.						
	18-356057	0%										
	18-356058	0%										
packaging storeroom	19-356059	0%	acoustical tile	OMG	35	sq.ft.						
scheduling office	19-356059	0%	acoustical tile	OMG	144	sq.ft.						
north packaging office	19-356059	0%	acoustical tile	OMG	180	sq.ft.						
center packaging office	19-356059	0%	acoustical tile	OMG	168	sq.ft.						
south packaging office	19-356059	0%	acoustical tile	OMG	168	sq.ft.						
	19-356060	0%										
	19-356061	0%										

AREA COMMENTS

AREA # 10 TOTAL \$0 \$0 \$0

*****	AREA NUMBER: 11	AREA DESCRIPTION: 2nd Floor-Mezzanine Area	AREA AVERAGE % ASBESTOS: 15%	*****
-------	-----------------	--	------------------------------	-------

LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	QUANTITY	UNITS OF MEASURE	PIPE ID	EXP POT	PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
mezzanine-SE corner-above heater unit	20-356062	6%	debris	OMF	3	sq.ft.		62	I	\$100	\$0	\$100
	20-356063	10%						62	I			
	20-356064	30%						62	I			

AREA COMMENTS

AREA # 11 TOTAL \$100 \$0 \$100

The debris is located above the heater unit in the southeast corner. The debris should be removed. Gross removal procedures are recommended for removal.

BUILDING # 35 TOTAL \$36,746 \$22,939 \$59,685